

May 15, 2019

Connie Gonzalez Principal Bayview Child Development Center 2485 Felspar St. San Diego, CA 92109

Subject: Bayview CDC Drinking Water Project Closeout

Dear Mrs. Gonzalez:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Bayview CDC campus.

As part of a Districtwide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Bayview CDC for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Bayview CDC campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto Manager, Facilities Planning



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Bayview CDC Report Type: Closeout Report Date of Report: 05/15/19

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
	2 Admin/Kitchen - Bayview CDC_02-02 Common Area/Lounge - LGE1, West Wall	DWO-834-001	Faucet	3.47		
2	2 Admin/Kitchen - Bayview CDC_02-02 Food Serving, North Wall	DWO-834-003	Faucet	6.39	FLTR	ND
3	3 Classroom 2 - Bayview CDC_02-03 Classroom - 02, East Wall	DWO-834-004	Drinking Fountain Bubbler	<5		
	4 Classroom 3 - Bayview CDC_02-04 Classroom - 03, South Wall	DWO-834-005	Drinking Fountain Bubbler	<5		
5	5 Restrooms - Bayview CDC_02-05 Building Exterior, North Wall	DWO-834-006	Drinking Fountain Bubbler	<5		
6	5 Restrooms - Bayview CDC_02-05 Building Exterior, North Wall	DWO-834-007	Drinking Fountain Bubbler	<5		
	Portable K03 - Bayview CDC Classroom - K03 Kinder, Island Counter	DWO-834-008	Drinking Fountain Bubbler	<5		

*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.