

Environmental Monitoring and Technical Services 2392 Kincaid Road MS 45A. San Diego, CA 92101 Tel(619) 758-2300 Fax (619) 758-2309

Lead School Testing Report Date: 5/17/17

San Diego Unified School District **Angier Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168186	04/22/17	08:43 AM	SAMPLE 1	3710020-AJG-A	< 5	ug/L
W1168187	04/22/17	08:45 AM	SAMPLE 2	3710020-AJG-B	< 5	ug/L
W1168188	04/22/17	08:49 AM	SAMPLE 3	3710020-AJG-C	10.2	ug/L
W1168189	04/22/17	08:51 AM	SAMPLE 4	3710020-AJG-D	< 5	ug/L
W1168190	04/22/17	08:55 AM	SAMPLE 5	3710020-AJG-E	< 5	ug/L

Source	Source Description
SAMPLE 1	Lunch Court area near room 9; Far Left bubbler of exterior fountains closest to girls RR
SAMPLE 2	Exterior next to room 16; two triple fountains, right bubbler on right fountain
SAMPLE 3	Cafeteria/Kitchen; South interior wall in the corner in Kitchen; Spray faucet
SAMPLE 4	West exterior wall next to custodial room; Two double fountains, right bubbler of right fountain
SAMPLE 5	Kindergarten; Inside K-2; bubbler on the right side of sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L $\,$